

RECEIVED

JAN 26 1993

DIVISION OF  
OIL GAS & MINING

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

### ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

#### I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) Jan. 1992 To (mo./yr.) Dec. 1992
2. DOGM File Number: M /045 /002
3. Mine Name: Reilly Wendover
4. Mineral(s) Mined: Potash
5. Legal Description (Location of Lands Affected):  
       1/4,        1/4, Section       , Township       , Range         
       1/4,        1/4, Section       , Township       , Range         
       1/4,        1/4, Section       , Township       , Range
6. Name of Operator or Company: Reilly Wendover
7. Permanent Address: P.O. Box 580  
Wendover, Utah 84083

8. Company Representative (or designated operator):

Name: Glenn D. Wadsworth

Title: Plant Manager

Address: P.O. Box 580 Wendover, Utah 84083

Phone: (801) 665-2241

☐ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☒ No ☐

2. If active, how much ore or mineral was mined? 271,300 st.

3. How much new or additional acreage was affected during past year? 11.6

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

Constructed new Transfer Ditch 1,385,000 yds

Constructed new Collection Ditch 887,000 yds

Constructed new Barrow Ditch 792,000 yds

5. How much acreage was **reclaimed** during past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

All areas remained active in 1992

7. What is the **total disturbed acreage** at years end? 164 Acres
8. Briefly summarize mining and reclamation planned for the upcoming year.  
The mine is scheduled to remain operational during 1993. All areas for  
brine collection will continue to be cleaned. All additional areas will  
continue to be utilized for mining.

**NOTE:** Section III., "Additional Information" applies only to large mining operations.

### III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

### IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Glenn D. Wadsworth

Title of Operator: Plant Manager

Signature of Operator: 

Date: 01/25/93


jb  
MR-AR



**REILLY  
WENDOVER**


WENDOVER, UTAH

EVAPORATION PONDS  
&  
COLLECTION AREA



LEGEND

NEW DITCH  
COLLECTION DITCH  
BARROW DITCH  
TRANSFER DITCH  
POND LINE  
PROJECTED PRIMARY POND  
PROJECTED SPRING POND  
PROJECTED WASTEWATER POND  
PONDING LEASE  
UTAH STATE LEASE  
POND SYSTEM ID



New Transfer Ditch  
New Collection Ditch  
New Barrow Ditch

